
UWFPS Twin Otter Telecon, November 7 2016



- 1. Instrument updates
- 2. Current conditions in Salt Lake City
- 3. Potential updates to campaign schedule
- 4. New constraints on twin otter payload and some hard choices ☺
- 5. Consumables ordering
- 6. Hazardous materials
- 7. Other items (to be decided between now and the next telecon)



Potential Updates to Schedule

As of October 18, revised signed aircraft allocation from OMAO gives our project 86 hours and 38 days, a slight reduction

- January 2 integration start is still firm
- January 15 transit to Salt Lake is still firm
- February 13 transit back to Colorado may shift by one week if no further allocation or purchase of flight days or hours
- The aircraft is available to us through February 13, so:
 Aircraft allocation may shift back to the full duration
 CSD may consider funding the extra week

For now, please plan on campaign conclusion on February 15 as originally planned, but stay tuned for updates as this process moves forward

Site Visit to Salt Lake

Steve will visit Salt Lake this week and tour the TAC air hangar and ground sites with Munkh. Ron Pauley of NOAA / AOC will join visit to the hangar on November 10.

Logistical items to be discussed at hangar

Space for instruments and equipment
Hazardous materials and storage
Aircraft power arrangement for non-flight days, pre-flights and in between flights (Ron)
Badging and security

Other?

Payload Constraints

Recent changes have pushed the payload above the previously established limit

- 1. AMS weight has increased by 40-60 lbs
- 2. NH3 QCL cannot operate without large pump and extra gas cylinder, increase of ~50 lbs
- 3. AOC has informed us of life raft requirement, increase of 70 lbs
- 4. Picarro is now available again. Good news, except 70 lbs of payload

Instrument Priorities (my view)

- 1. AMS
- 2. I- CIMS
- 3 & 4. NOxCaRD and NH3 QCL (tie)
- 5. UHSAS
- 6. Picarro

Options

- 1. AMS + I⁻ CIMS + (NOxCaRD or NH3 QCL) + UHSAS + Picarro + 2 operators Decide between NOxCaRD or NH3 QCL
 - Explore possibility of swapping NOxCaRD and NH3 QCL mid campaign
- 2. AMS + I⁻ CIMS + NOxCaRD + NH3 QCL + 1 operator (no Picarro or UHSAS)

Revised Payload Option 1

Instrument	Power (kVA)	Weight (lbs)	Actual Power (kVA)	Actual Weight (lbs)	Notes
AMS	1.1	560	1.1	560	
lodide TOF CIMS	1	380	1	380	
NOxCaRD	0.5	286	0.5	286	
NH3 QCL	0.93	219	0	0	
Picarro CO (CH4)	0.4	70	0.4	70	
Met Probe	0.1	7	0.1	7	
Data Acquisition	0.1	10	0.1	10	Estimate
UHSAS	0.1	49	0.1	49	
Equipment Subtotal		1581		1362	
Pilots		360		360	2 pilots
Scientists		360		360	2 operators
Life raft		70		70	
Crew Subtotal		790		790	
Total	3.93	2371	3	2152	
Available	4 kVA 115 VAC ~3 kVA 28 VDC	2200	5	2200	

Revised Payload Option 2

Instrument	Power (kVA)	Weight (lbs)	Actual Power (kVA)	Actual Weight (lbs)	Notes
AMS	1.1	560	1.1	560	
lodide TOF CIMS	1	380	1	380	
NOxCaRD	0.5	286	0.5	286	
NH3 QCL	0.93	219	0.93	219	
Picarro CO (CH4)	0.4	70	0	0	
Met Probe	0.1	7	0.1	7	
Data Acquisition	0.1	10	0.1	10	Estimate
UHSAS	0.1	49	0	0	
Equipment Subtotal		1581		1462	
Pilots		360		360	2 pilots
Scientists		360		180	1 operator
Life raft		70		70	
Crew Subtotal		790		610	
Total	3.93	2371	3.53	2072	
Available	4 kVA 115 VAC ~3 kVA 28 VDC	2200	5	2200	

Consumables Ordering

Compressed Gases

Based on 15 research flight days in Salt Lake City, 1-2 test flight days + transit from RAF

I- CIMS

RAF: 4 size 50 A UHP N2 + 1 size 150 A UHPN2

Salt Lake: 17 size 50 A UHP N2 + 4 size 150 A UHP N2

NOxCaRD & NH3 QCL (each instrument has the same zero air requirements)

RAF: 4 size 50 A Ultra Zero Air + 1 size 150 A Ultra Zero Air

Salt Lake: 17 size 50 A Ultra Zero Air + 4 size 150 A Ultra Zero Air

NOxCaRD will additionally use 2 size 150 A 2 ppth NO in N2 shipped to Boulder only

AMS:

Will share zero air with NOxCaRD

Other consumables

University of Washington has provided a purchasing list – will coordinate with them

If other groups need consumables purchased and shipped to Boulder / RAF / Salt Lake, please notify me ASAP

Hazardous Materials – Salt Lake City Hangar

UWFPS Twin Otter Project - Hazardous Materials List							
Instrument	Item	Unit	Quantity	UN#	Notes		
NOCaDD	Communicated air	FO #2 . 2200 mail	17		1002		
NOxCaRD	Compressed air	50 ft3, 2200 psi	4		1002		
	Compressed air	150 ft3, 2200 psi	3				
	Oxygen	6 ft3, 2200 psi	3		1072		
	Nitric oxide in N2, 0.2%	6 ft3, 2200 psi	1		1956		
	Helium	6 ft3, 2200 psi	1		1046		
	Acetone	100 mL			1090		
	Methanol	100 mL	1		1230		
	Purafil SP Media (NOx scrubber)	1 Kg	1		Purafil		
	Envicat (Catalytic O3 scrubber)	1 Kg	1				
AMS	Helium	35 ft3	1		1046		
	Ammonium nitrate	25 g	1		1492		
	Ammonium sulfate	25 g	1	Not danged	ours goods		
	Apiezon L grease	25 g	1	Not danged	_		
	Methanol	500 ml	1		1230		
	Mini-Buck soap solution	100 ml	1	Not danged			
	n-Butanol	500 ml	1		1120		
	polonium-210	740 MBq	1		2915		
	polystyrene latex spheres in water	120 ml	1	Not danged			
	Silica gel	2 kg	1	Not danged	=		
I- CIMS	Compressed nitrogen	50 ft3, 2200 psi	17		066		
	Compressed nitrogen	150 ft3, 2200 psi	4	10	066		
	Methyl iodide	< 5g	1				
	polonium-210	740 MBq	1	29	915		
NH3 QCL	Compressed air	50 ft3, 2200 psi	17		1002		
	Compressed air	150 ft3, 2200 psi	4		1002		
	Silicon ortho phosphate	1 L	1		Ammonia scrubbing media		
	Carbon	2 L	1		Purakol		
	Potassium permaganate	2 L	1		Purafil		
	Ethyl alcohol	4 L	1		1987 Chiller (will be prepared as 20% solution)		
	Ammonia	-	1		1005 Permeation device		
	Perfluorooctylamine	10 g	1		2735 Inlet passiviation		
	i ernaorooctylainine	10 g			2733 milet passiviation		

Hazardous Materials – Salt Lake City Hangar

- Please check the hazmat list for completeness
- If you have not already sent me your MSDS for these items, please do so. I will store them electronically and provide paper copies in binders organized by instrument
- Please identify which items on your instrument list will be installed in the aircraft

Other Items

- 1. Firm schedule for integration
- 2. Shipping of instruments and equipment to Boulder / RAF / Salt Lake
- 3. Shipping between RAF and Salt Lake
- 4. Travel arrangements & schedules